Statement of Return

Storgatan 81
352 36 Växjö
SWE

Vehicle Details

Reg No.	BYO171
Serial No.	134770
Vehicle desc.	SEAT ARONA 1.0 TSI 115 DSG7 ST
Color	SILVER
Fuel type	Bensin

Rental Details

Rental order No.	111339686
Driver name	STEPHEN CROALL
Checkout station	Malmö City
Checkout date/time	8/16/2019 9:00 AM
Checkin station	Växjö
Checkin date/time	8/16/2019 4:00 PM

Meter reading out	11,157.000
Meter reading in	12,553.000
Km driven	247
Estimated tank level*	8/8

*Please notice that vehicle will be refueled and that additional costs may apply.

Damages



(A) = Minor damage (B) = Medium damage (C) = Extensive damage

Existing damages

(B) - Back and roof - Back bumper - Skrap pskada
(B) - Other - Other - Fläck på höger säte bak.
(A) - Back and roof - Back bumper - Märke ej genom lack
(A) - Passenger side - Right front door - Liten buckla med jätteliten märke ovanför handtaget

New damages

A full inspection of the car can only be made after a completed outside wash and inside cleaning

Statement of Return

New Damages

Detachable equipment

	Checkout	Checkin
Boot cargo cover	X	X
Flat tyre equipment	X	X
Warning Triangle Red	X	X
Carpet floor mats	X	X

Rented extra equipment

Warning lights

Parking place

Other remarks

Signature

Due to these signatures both parties confirm the documented condition of rented vehicle.
All data are subject to change

2019-08-16	Customer not present	
Date	STEPHEN CROALL (Customer signature)	Jacobsson Benjamin (Station agent signature)

Damage Photos